


~~SECRET~~SAPC 18435  
COPY 1 OF 1CMCC Document No. 151X5.654  
Copy 2 of 4

25X1A

1 August 1957

To:  WRSP-3)

From:

Info: Headquarters

25X1A 12/11/81 REVIEWER: 037169

Reference: Special Technical Report from  dated  
28 June 1957 (with information copy to Headquarters)

The guide roller, MP10095, is contained in the depot stock and may be requisitioned to replace defective parts encountered in the field.

I disapproved the addition of guide roller MP10095 to the FAK list. The reasons are as follows:


1. In two years of operation spread over seven geographic locations, this was the first usage of this item.
2. When such low-usage items are contained in the FAK, the parts must be re-ordered immediately upon issue.
  - a. Such low-usage items are not stocked at the factory, and the production of one item to replace the FAK is expensive and impractical.
  - b. The FAK lists were revised to pool the low-usage items and thereby eliminate small quantity production of such items.
  - c. This procedure does not deprive the field units of access to these parts. The time required to requisition the stock from the depot is less than the time required to make changes in the FAK.

The information and suggestions received from the field units are an important part of the contributions making up a successful operation. In this particular case I believe the misunderstanding can be attributed to the field units not knowing what is available in depot stock.

In a later report from Sandler (no date on report) came information and suggestions regarding the recorder timing oscillators and the tension on the System 1 recorder feed-loop arm. These comments will be passed on to the appropriate people.

25X1A

PWA:hcp

~~SECRET~~